



WARRANTY

Cappsco International Corp represents and warrants that their workmanship conforms to the intent of the manufacturer's requirements and that all workmanship is in compliance with Federal Aviation Administration regulations.

Engine assemblies overhauled by Cappsco International are warranted to be free from defects in workmanship performed by Cappsco for a period of 1000 hours or 18 (eighteen) months (whichever first) but in NO CASE to extend more than 18 months after work completion date unless prior written agreement has been made for extended storage.

Accessories, Components, Fuel Control's and Overspeed Governor's overhauled by Cappsco International are warranted to be free from defects in workmanship performed by Cappsco International for a period of 300 hours or 6 (six) months (whichever occurs first) but in NO CASE to extend more that 6 (six) months after work completion date unless prior written agreement has been made for extended storage.

Cappsco's liability is limited to the time continued repair or overhaul at its facility, and its option on the defective parts or accessories overhauled or repaired by Cappsco which are determined by Cappsco to have been defective due to faulty workmanship by Cappsco. Warranty allowances shall not exceed the net price shown on the original overhaul/repair invoice.

The responsibility of Cappsco under this warranty is further limited by the following conditions:


1. Defects in workmanship must be discovered before the manufacturer's recommended time between overhaul or calendar life of warranty has elapsed; in NO CASE shall our warranty have any extension.

2. The engine and/or components must have been installed, preserved, maintained and operated in accordance with manufacturer's directive and instructions and within applicable limitations. Based on our review of catastrophic engine failures, Cappsco strongly recommends that the fuel manifolds be removed, cleaned, flow tested, certified and properly reinstalled at intervals of no greater than 600 hours.

The engine and components must not have been altered or repaired outside of Cappsco facilities and the engine and components must not have been subjected to misuse, neglect, accident, or damage from the elements.



CAPPSCO INTERNATIONAL CORP.



FAA Repair Station #X02R0270

Pg 2 – Warranty Continued

3. The engine, and accessory components must be returned to Cappsco's facility after notice of failure has been given, and Cappsco must be afforded the opportunity to perform corrective work at the facility of its choice (unless such work is otherwise authorized in writing by Cappsco).

Cappsco is not a manufacturer of parts and does not warrant parts, materials, or services that are relative to, or included in parts manufacturer, but we do agree to use our best efforts to insure that the suppliers, manufacturers, and subcontractor's warranties (with respect to such parts, materials, and services) will be extended to cover and be enforceable by the customer. Cappsco will act for its customers in the processing of any claims or adjustments arising out of, and because of, defective parts, materials and workmanship in accordance with such supplier's and subcontractor's warranties.

This warranty is extended to the Customer at the time of delivery and may not be assigned without Cappsco's prior written consent.

Cappsco, when notified of possible warranty condition, will communicate with customer to arrive at possible solution to problem. If required, Cappsco will send a qualified representative to evaluate warranty problem. If the problem is a warranty issue, Cappsco will pay all expenses of our representative and return of the engine, if required. If the problem IS NOT a warranty problem, the customer and Gary Capps will arrive at a mutually agreeable settlement.